



Silicon Motion, Inc.

SM32X Test Program and ISP Release Note

**SM3257 Test Program and ISP Release Note:**

Release Date	ISP Version	ISP Check Sum	Test AP Version	Description
2010/06/07	SM3257AA 2010-06-07 SM3257AA 2010-06-07	SM3257AAISP 0x005ABF6E SM3257AAISP-bucket01 0x005A981D	V2.03.28 V5 10/06/07 build	<ol style="list-style-type: none">1. SM3257AAISP support Samsung 32nm TLC bucket00 flash K9ABG08U0A, K9BCG08U1A and K9CDG08U5A2. SM3257AAISP support Samsung 27nm MLC K9GBG08U0A3. SM3257AAISP-bucket01 support Samsung 32nm TLC bucket01 flash K9ABG08U0A, K9BCG08U1A and K9CDG08U5A.
2010/07/02	SM3257AA 2010-07-02	SM3257AAISP 0x005D3C3E SM3257AAISP-bucket01 0x005D12F0	V2.03.29 V3 10/07/02 build	<ol style="list-style-type: none">1. SM3257AAISP support Samsung 32nm MLC2. SM3257AAISP support Intel/Micron L74A3. SM3257AAISP support Intel/Micron L73A4. SM3257AAISP enhance suddenly power cycling protection5. SM3257AAISP-bucket01 enhance suddenly power cycling protection6. SM3257AAISP support Hynix 26nm MLC.7. MP tool fixed device disconnection issue when MP tool initial card.